



Product Bulletin

WB PURGE 100

WB Purge 100 is a safe purge solvent for removing paint residues from pumps, feed transfer lines, spray hoses, nozzles, application lines and equipment. It contains a combination of HAPS free solvents that lift and remove paint. **WB Purge 100** does not have dangerous chlorinated or flammable ingredients and will replace other common purge solvents like MEK, Xylene, Toluene, Acetone, Ketones, Esters and Naphthas now being used.

Features and Benefits

- HAPS Free Solvents
- Ready to use
- Higher Flash Point
- Effective Removal Of Most Paints And Resins

Typical Properties

Appearance	Clear Liquid
Density	7.53 lbs per gallon
Specific Gravity	0.902
Flash Point	105 F
V.O.C. Content	7.524 lbs per gallon

Application Procedure

WB Purge 100 is used full strength. Run solvent through lines and spray heads until clean. Drain or pump spent solvent from lines after cleaning. Blow lines out with air before reusing for painting. **WB Purge 100** can be used in a soak tank to clean parts. Submerge part to be cleaned in solvent until uncured paint is released or dissolved.

Consult Material Safety Data Sheet for handling and storage instructions before use.